



12 JANUARY 2010 EVENT

- ❑ Typical Earthquake Damage
- ❑ Repair Technical

Masonry Shear wall Crack (Window)



Minor Cracks



Masonry Shear wall Crack (X-Crack)



Wall out of plane Failure



Partially disconnected wall




Concrete Column Rupture




Spalled Concrete Column




Repair Technical




Repair Technical



Repair Technical



Repair Technical



Repair Technical

